Part No. 49217 Revised: June 2004

6 oz. Kettle Poppers

With / Love My Popper Kettle

Popcorn Machine Instruction Manual Models: 1871,2660,2661









Cincinnati, OH 45241-4807 USA

SAFETY PRECAUTIONS



A DANGER

Machine must be properly grounded to prevent electrical shock to personnel.

Do NOT immerse the kettle, warmer, or any other part of this equipment in water.

Always unplug the equipment before cleaning or servicing.



WARNING

Any alterations to this equipment will void the warranty and may cause a dangerous situation. NEVER make alterations to the equipment.

Make sure all machine switches are in the OFF position before plugging the equipment into a receptacle.



A WARNING

To avoid serious burns, do NOT touch the kettle while it is hot.



A WARNING

Adequate eye protection must be used when servicing this equipment to prevent the possibility of injury.



A CAUTION

This equipment is designed and sold for commercial use only. This equipment is not to be used by the consumer in home use. Do not allow direct contact of this equipment by the public when used in food service locations. Only personnel trained and experienced in the equipment operation may operate this equipment.

Carefully read all installation instructions before operating the equipment.

NOTE

The information, specifications and illustrations contained in this manual represent the latest data available at time of publication. Right is reserved to make changes as required at the discretion of Gold Medal Products Company without notice.

2 Models: 1871,2660,2661

INSTALLATION INSTRUCTIONS

INSTALLATION

Your new 6 oz. popcorn machine is completely assembled. Remove all Packing material and tape before starting operation.

OPERATING INSTRUCTIONS

CONTROLS AND THEIR FUNCTIONS

There are three switches on the popper.

LIGHT AND WARMER SWITCH

Turns on the heat to the bottom corn pan and heat light.

KETTLE MOTOR SWITCH

Turns on the motor which drives kettle agitator shaft.

KETTLE HEAT SWITCH

Turns on the heat element

POPPING INSTRUCTIONS

- 1. Turn KETTLE HEAT and KETTLE MOTOR switch ON.
- 2. Make test pop by putting 3 kernels of corn and 1 oz. (30 ml) of oil into the kettle.
- 3. When the 3 kernels have popped, load kettle with corn and oil charge.
- 4. When corn has popped, dump kettle.
- 5. Repeat cycle starting with Item #3; always pop 3-5 batches for best popcorn.

3



Models: 1871,2660,2661